

Carl's Oil 25

Technical data sheet

Carl's Oil 25 is a hardening pine oil for regular maintenance of oiled wooden floors. By frequently re-saturating the wood with Carl's Oil 25, the surface will keep looking its best and maintain its ability to resist wear and spills.

- For regular maintenance
- Fast drying

Technical data

Type of oil:	Esterified pine oil
Solids content:	Approx. 25 %
VOC:	600 g/litre
Density:	0.80 kg/dm ³
Dilution:	Do not dilute
Waiting time between applications:	30-45 minutes
Application tools:	Buffing machine with red pad and cloth
Total consumption:	Approx. 20-100 m ² /litre depending on type of wood and application method
Safety:	Classified (see the Safety Data Sheet)
Fire risk:	Yes (see the Safety Data Sheet)
Flash point:	36°C
Shelf life:	At least 2 years, from the date of production, in unopened original container
Storage:	Store frost-free
Pack size:	2 x 5 litres (35 boxes per pallet) 6 x 1 litre (72 boxes per pallet)

Preparations

Vacuum clean to remove loose dirt. Then clean the floor with a cleaner/ water solution, approx. 0.2 litre Carl's Cleaner to 10 litres of water. (For further information see Carl's Cleaner.)

Application

When the floor is absolutely dry apply a thin layer of Carl's 25 using a cotton cloth or similar. On large areas apply the oil using a buffing machine: Put the cloth on the floor, place a red pad on the cloth and pour ca 0.1 litre oil in the middle of the pad. Spread the oil evenly on ca 10 m², add more oil as required, and continue until the whole floor surface has got a thin layer of oil. Move the machine in alternate directions and finish along the grain. On the edges and in the corners the oil should be applied by hand with a cotton cloth.

Floor Care



Bona[®]

Carl's Oil 25

Technical data sheet

Floor Care



WARNING: CARL'S OIL 25 CONTAINS DRYING OILS. RISK OF SELF-IGNITION. USED CLOTHS, RAGS AND SIMILAR SHOULD BE PLACED IN WATER OR SEALED METAL CONTAINERS.

Allow the floor to dry for at least 1 hour. Afterwards buff it with a red pad under the machine. Move the machine in alternate directions and finish along the grain.

Allow the floor to dry for 12 hours without any foot traffic.

Maintenance

Clean the floor on a daily basis using a dry mop and/or a vacuum cleaner. When necessary, wipe off with a damp mop with Bona Soap added to the cleaning water. N.B. Always clean using as dry a method as possible.

Bona[®]